



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



Cert. No : KLR 0403591

NOTICE TO MARINERS NTM 60 (T)/2013

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Strait of Malacca

Charts Affected : MAL 532 & BA 3946

TEMPORARY BUOY MARKING AT KUALA SUNGAI LINGGI

Mariners are advised that an isolated danger mark light buoy is temporarily established at the following location:

Name : Unknown Wreck

Type : Isolated Danger Mark

Position : Lat 02°19.42' N Long 101°57.63' E

Light Characteristic : Fl.(2) 10s

Mariners are advised to navigate with extra caution when in the vicinity.

(MOHD NAZWAN HAFEEZ BIN HASHIM)

for The Director General,
Marine Department Malaysia.

21th June 2013

“Ke Arah Negara Kelautan Elektronik”
“Towards e-Maritime Nation”

